



Firmware Update for Certain Pioneer In-Dash AV Receivers

Jui 1, 2026

Dear Valued Pioneer Customer:

We would like to inform you of the availability of a firmware update for **only for the following Pioneer In-Dash AV Receivers sold in Australia & New Zealand. Installation on any other product could cause irreversible damage.**

DMH-ZF7650BT

This firmware update corrects the following matter.

- Fixed an audio issue that occurred when switching tracks during music playback in CarPlay.
- Improved smartphone connectivity.
- Minor bug fixes

To perform this update, the following items are needed:

- Select Pioneer In-Dash AV Receiver
- Blank USB storage device (no files), 512 MB or larger in capacity, formatted to FAT32 or NTFS.

Instructions on installing the firmware are provided on the same page as the firmware update. Installation of the update should take about fifteen minutes to complete.

How to Obtain the Free Firmware Update:

1. Download the firmware update files to a computer from the Pioneer website:
<https://www.pioneer.com.au/firmwaresoftware/>
2. Transfer the files to the USB storage device for insertion into the Pioneer In-Dash AV Receiver.

Questions

If you have any questions, please contact Pioneer Technical Support team on 1800 988 268, Monday through Friday, 9:00 AM - 4:30 PM (excluding holidays).

Sincerely,

Pioneer Electronics Australia Pty Ltd